

Estate **Rosebank**

Date **29 September 2021**

Date of next walkabout

Number of Attendees **2**



Street Name	Issue Identified	Action Agreed	Target Completion Date	Status	Notes	Actual Completion Date
Rosebank Place	Outside light above main entrance door is not working	Raise line for electrician	31/10/2021	COMPLETE		05/10/2021
Rosebank Place	Trees in following locations are overgrown S19, S17, S14 and S13	Add to winter maintenance	30/09/2021	COMPLETE	Added	30/09/2021
Rosebank Place	Northern end (S28) Tree on kerbside is leaning and roots are protruding from ground	Inform Dean Lyon	30/09/2021	COMPLETE	Dean Emailed	30/09/2021
Rosebank Place	Drying greens x 2 moss on pathways is a slip hazard	Inform Dean Lyon	30/09/2021	COMPLETE	Dean Emailed	30/09/2021
Rosebank Place	NE corner of complex S28 Shrubs adjacent to block are overgrown, blocking air vents and reaching up to flat windows	Inform Dean Lyon	30/09/2021	COMPLETE	Dean Emailed	30/09/2021
Rosebank Place	Northern end of Rosebank Place - Small fly tip in hedges - polystyrene box etc	Leif to arrange uplift	31/10/2021	PENDING		
Hilltown	Joint on rooftop guttering is leaking	Raise line to replace	31/10/2021	COMPLETE		01/10/2021
Rosebank Place	Graffiti on wall adjacent to side alley	Raise line to remove	31/10/2021	PENDING		
Rosebank Place	Rooftop guttering above front door to flat is blocked	Raise line for roofer	31/10/2021	COMPLETE		01/10/2021
Rosebank Place	Moss on paving is slip hazard	Inform Dean Lyon	30/09/2021	COMPLETE	Dean emailed	30/09/2021
Rosebank Place	Guttering above patio entrance is blocked	Raise line for roofer	31/10/2021	COMPLETE		01/10/2021