

Percentage of properties meeting the EESSH (Indicator C33)

C33.1 Number of self contained properties

	Gas	Electric	Other fuels	Total
Flats	918	97	1	1,016
Four-in-a-block	123	0	0	123
Houses (other than detached)	467	157	2	626
Detached houses	3	9	0	12
Total	1,511	263	3	1,777

C33.2 Number of self contained properties not in scope of the EESSH

	Gas	Electric	Other fuels	Total
Flats	0	0	0	0
Four-in-a-block	0	0	0	0
Houses (other than detached)	0	0	0	0
Detached houses	0	0	0	0
Total	0	0	0	0

C33.3 Number of self contained properties in scope of the EESSH

	Gas	Electric	Other fuels	Total
Flats	918	97	是如此是551	1,016
Four-in-a-block	123	0	0	123
Houses (other than detached)	467	157	2	626
Detached houses	3	9	0	12
Total	1,511	263	3	1,777

C33.4.1 Number of properties in scope of the EESSH where compliance is unknown

	Gas	Electric	Other fuels	Total
Flats	66	0	0	66
Four-in-a-block	17	0	0	17
Houses (other than detached)	134	1	0	135
Detached houses	0	0	0	0
Total	217	1	0	218

C33.4.2 Where EESSH compliance is unknown for any properties, please explain why These are properties for which no actual EPC has been carried out to date or other information from which compliance can be demonstrated. They form part of targeted programme for future compliance and works.

C33.5 Number of properties in scope of the EESSH that do not meet the standard

	Gas	Electric	Other fuels	Total
Flats	107	6	0	113
Four-in-a-block	7	0	0	7
Houses (other than detached)	130	11	0	141
Detached houses	0	0	0	0
Total	244	17	0	261

C33.6 Number of properties in scope of the EESSH that are exempt the standard

	Gas	Electric	Other fuels	Total
Flats	0	0	0	0
Four-in-a-block	0	0	0	0
Houses (other than detached)	0	0	0	0
Detached houses	0	0	0	0
Total	0	0	0	0

C33.7 Number of properties in scope of the EESSH that meet the standard

	Gas	Electric	Other fuels	Total
Flats	745	91	1	837
Four-in-a-block	99	0	0	99
Houses (other than detached)	203	145	2	350
Detached houses	3	9	0	12
Total	1,050	245	3	1,298

Percentage of properties meeting the EESSH (Indicator C33)

73.0 %



Working towards the EESSH (Indicator C34)

C34.1 Number of properties you estimated to bring up to the EESSH during the reporting year

	Gas	Electric	Other fuels	Total
Flats	20	0	0	20
Four-in-a-block	0	0	0	0
Houses (other than detached)	3	0	0	3
Detached houses	0	0	0	0
Total	23	0	0	23

C34.2 Number of properties brought up to the EESSH during the reporting year

	Gas	Electric	Other fuels	Total
Flats	40	0	0	40
Four-in-a-block	0	0	0	0
Houses (other than detached)	10	0	0	10
Detached houses	0	0	0	0
Total	50	0	0	50

C34.3 If the figures at C34.1 and C34.2 are different, please explain why

- 1. Improvements in recording procedures
- 2. Ad-hoc works as a result of stock condition surveys.
- 3. External Fabric Works Programme has led to improvements in scores retesting after programme carried out

C34.4 The number of properties you estimate to bring up to the EESSH in the next reporting year

	Gas	Electric	Other fuels	Total
Flats	42	0	0	42
Four-in-a-block	0	0	0	0
Houses (other than detached)	10	0	0	10
Detached houses	0	0	0	0
Total	52	0	0	52



Page 4 of 8

Abertay Housing Association Ltd EESSH Return 2018-19

Anticipated exemptions from the EESSH (Indicator C35)

C35.1 Number of properties you anticipate will require an exemption from the first EESSH milestone in 2020

	Gas	Electric	Other fuels	Total
Flats	21	5	0	26
Four-in-a-block	0	0	0	0
Houses (other than detached)	143	2	0	145
Detached houses	0	0	0	0
Total	164	7	0	171

C35.2 The reasons you anticipate properties will require an exemption

Technical	40
Social	11
Excessive cost	120
New technology	0
Legal	0
Disposal	0
Long term voids	0
Unable to secure funding	0
Other reason / unknown	0

C35.3 If other reason or unknown, please explain

- 1. This assessment is based upon those currently known as failures and knowledge of those we have yet to fully survey
- 2. These are properties within our stock where previous insulation or heating upgrades have been refused by tenants. It is possible that these works will not have been carried out prior to 2020.
- 3. We anticipate that some works will not be econimically viable. The savings returned



Energy Performance Certificates (EPCs) (Indicator C36)

C36 1 EPC rating

	C36.1.1 The number of	C36.1.2 The number of
	properties with a valid	EPCs lodged in the
	EPC	reporting year
Α	0	0
В	115	65
С	844	94
D	264	34
E	46	0
F	6	0
G	1	0
Total	1,276	193

C36.2 Of the properties with a valid EPC, please state which version of the SAP was used for generating the EPCs

SAP 2001	0	
SAP 2005	173	
SAP 2009	398	
SAP 2012	660	
Other procedure / unknown	45	

	C36.3 if other procedure or unknown, please explain				
Certificates do not state method on them					



Investment in the EESSH (Indicator C37)

C37.1 The total number of properties brought up to the EESSH during the reporting year 50

C37.2 Of the total amount invested in bringing properties up to the EESSH, please state how much came from

C37.2.1 Subsidy

C37.2.2 The landlord's own financial resource 567,412

C37.2.3 Another source

C37.2.4 Total amount invested in bringing properties up to the EESSH 567,412

C37.3 Please give reasons for any investment which came from another source



Validation Summary

The sum of all C35.2 must equal C35.1 Total



Α	n	n	r	0	V	a	۱
т	μ	ν		v	v	а	в

Chair

Under exceptional circumstances, if the return is to be approved with validation messages showing
on your Validation Summary, you must provide reason(s) why these cannot be cleared:
The validation summary says the sum of all C35.2 must equal C35.1 total. C35.1 total
is 171 and the figures in C35.2 are 40, 11 & 120 which add to 171

We confirm that this organisation has completed this return in accordance with the Technical Guidance and has been reviewed and approved by the Governing Body at its meeting on:

Date of Approval
29 May 2019

Name of Approver

Kath Mands

Job Role of Approver

Submit to SHR