

Estate **Fintry South 2**Date **25 March 2026**Date of next walkabout **01 April 2026**Number of Attendees **1**

Street Name	Issue Identified	Action Agreed	Target Completion Date	Status	Notes	Actual Completion Date
Finlaggan Crescent	Litter o/s ground right	noted for information only	00/01/1900	COMPLETE	noted for information only	25/03/2026
Finlaggan Crescent	Several chipped tiles at main entrance	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Finlaggan Crescent	Paint flaking on m/e walls	noted for information only	00/01/1900	COMPLETE	noted for information only	25/03/2026
Finlaggan Crescent	Old bike dumped in back area	letter to be sent	Gaynor Arcari	COMPLETE	letter to be sent	09/04/2026
Finlaggan Crescent	Chipped tile on ground floor stair by back door	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Finlaggan Crescent	Uneven slabs on top step at front	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Finlaggan Crescent	Gap in front of top slabs, need filling	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Finlaggan Crescent	Uneven slabs at top front steps	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	15/04/2026
Finlaggan Crescent	Litter outside G/L	Noted for information only	00/01/1900	COMPLETE	Noted for information only	25/03/2026
Finlaggan Crescent	Old toy on bottom landing	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Finlaggan Crescent	Graffiti on wall bottom floor	CST to raise line to remove	Customer Service Team	COMPLETE	CST to raise line to remove	08/04/2026
Finlaggan Crescent	Moss in back area	Email sent to Dean	Dean Lyon	PENDING	Email sent to Dean	
Finlaggan Crescent	Bikes and rubbish top landing	Letter to be sent to 2/L & 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/L & 2/R	09/04/2026
Finlaggan Crescent	Lots of shoes top landing	Letter to be sent to 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/R	09/04/2026
Finlaggan Crescent	Land opposite - van on verge	For info only	00/01/1900	COMPLETE	For info only	25/03/2026
Finlaggan Crescent	Uneven slabs and gap top front steps	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	15/04/2026
Finlaggan Crescent	Cardboard box in back area	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Finlaggan Crescent	Old pool in back area	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Finlaggan Crescent	Rubber tiles in back area	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Finlaggan Crescent	Bikes on top landings	Letter to be sent to 2/L & 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/L & 2/R	09/04/2026
Finlaggan Crescent	Unit on top landing	Letter to be sent to 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/R	09/04/2026
Fintry Crescent	Uneven slabs at top of steps	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	22/04/2026
Fintry Crescent	Chipped tile at main door	CST to raise line for repair	Customer Service Team	PENDING	CST to raise line for repair	
Fintry Crescent	Mattress at back door - inside close	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Fintry Crescent	Sofa out back garden	CST to raise line for S&S to uplift	Customer Service Team	PENDING	CST to raise line for S&S to uplift	
Fintry Crescent	Sheet of plywood out back	CST to raise line for S&S to uplift	Customer Service Team	PENDING	CST to raise line for S&S to uplift	
Fintry Crescent	Chipped tile at back door	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Fintry Crescent	Wall tiles, first floor landing breaking off	CST to raise line to repair/make safe	Customer Service Team	COMPLETE	CST to raise line to repair/make safe	14/04/2026
Fintry Crescent	Bikes hanging over railings top floor	Letter to be sent to 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/R	09/04/2026
Fintry Crescent	Broken tile beside back door	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Fintry Crescent	Broken bike chained to back fence	Letter to be sent to block	Gaynor Arcari	COMPLETE	Letter to be sent to block	09/04/2026
Fintry Crescent	Moss out back	Email sent to Dean	Dean Lyon	PENDING	Email sent to Dean	
Fintry Crescent	Loose tiles below stair on first floor	CST to raise line for repair	Customer Service Team	COMPLETE	CST to raise line for repair	14/04/2026
Fintry Crescent	Bike on top floor	Letter to be sent to 2/L & 2/R	Gaynor Arcari	COMPLETE	Letter to be sent to 2/L & 2/R	09/04/2026

Estate **Fintry South 2**

Date **25 March 2026**

Date of next walkabout **01 April 2026**

Number of Attendees **1**



Fintry Crescent	Cardboard boxes in front	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Fintry Crescent	Fridge Freezer out back	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Fintry Crescent	Mattress out back near bins	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Fintry Crescent	Mirror on stairwell	CST to raise line for S&S to uplift	Customer Service Team	COMPLETE	CST to raise line for S&S to uplift	09/04/2026
Fintry Crescent	Graffiti on top floor	CST to raise line to remove	Customer Service Team	COMPLETE	CST to raise line to remove	09/04/2026